


Hurd weather seal gap at casement; aged, hardened, seal vinyl surface is crazed (cracked)



Suspect interior seal gaps as well and leaks in metal cladding at seams; there were gaps (seal failure)